

# 11 - SPARE PARTS

## 11.1 WARNING FOR THE CUSTOMER

Before ordering any particular spare part, it is always necessary to specify the serial number of the machine to which the part shall fit.

## 11.2 DETAILED DRAWING OF 30.OL01 TP6/R MANUAL CUTTING MACHINE FOR TAPED RADIAL COMPONENTS P. 12.7

