


11.3 DETAILED DRAWING ADDITIONAL PLATE TP LN 500-1



11.3.1 READING KEY FOR DETAILED DRAWING ADDITIONAL PLATE TP LN 500-1

Pos.	Item	Description	Q.ty
1	340114	ADD.PLATE HEIGHT CHANGE H=0.5 (CUTT.AREA 52X43) FOR 340111	1
2	-----	SPECIAL SCREW TBEI M 4x4	2
3	-----	WASHER	2
1	34011416	ADD PLATE HEIGHT CHANGE H=1 (52X43) FOR TP/LN-500/1	1
2	-----	SPECIAL SCREW TBEI M 4x4.5	2
3	-----	WASHER	2
1	34011417	ADD PLATE HEIGHT CHANGE H=1.5 (52X43) FOR TP/LN-500/1	1
2	-----	SPECIAL SCREW TBEI M 4x5	2
3	-----	WASHER	2
1	34011418	ADD PLATE HEIGHT CHANGE H=2 [52X43) FOR TP/LN-500/1	1
2	-----	SPECIAL SCREW TBEI M 4x6	2
3	-----	WASHER	2
1	34011419	ADD PLATE HEIGHT CHANGE H=2.5 (52X43) FOR TP/LN-500/1	1
2	-----	SPECIAL SCREW TBEI M 4x6	2
3	-----	WASHER	2
1	34011420	ADD PLATE HEIGHT CHANGE H=3 (52X43) FOR TP/LN-500/1	1
2	-----	SPECIAL SCREW TBEI M 4x6.5	2
3	-----	WASHER	2
ADJUSTMENT TOOL SET			
A	350308		1